



## 交通部航港局航船布告

中華民國 112 年 1 月 4 日

### 6 礙航公告(中區)允能風力發電股份有限公司雲林風場水下基礎閃光浮標故障通告

依據 允能風力發電股份有限公司 111 年 12 月 30 日允字第 111123002 號函。  
旨揭公司編號 YUN56 單樁式水下基礎由於不明原因未能成功打設，該單樁頂端目前位於海平面下 20.9 公尺，位置座標為北緯 23 度 33 分 14.245 秒；東經 119 度 59 分 27.905 秒。

原以 3 座閃光浮標圍繞標示，惟目前因海氣象因素故障中，詳細資料如附件。

航行船隻，請避開該區域，注意航行以策安全。

位置 北緯 23°33'21.0"，東經 119°59'27.1"。  
北緯 23°33'11.0"，東經 119°59'34.2"。  
北緯 23°33'11.1"，東經 119°59'21.8"。  
北緯 23°33'14.2"，東經 119°59'27.9"。\*WGS84

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

January 4, 2023

**6**

Taiwan Yunlin Offshore – light buoys malfunction

Source  
Details

Yunneng Wind Power Co.,Ltd, letter No. 111123002 dated December 30, 2022.  
3 light buoys at Yunlin Offshore Wind Farm were malfunctioning. Please refer to attachment.

Positions

Please all vessels avoid this area and pay attention to navigation for safety.

Lat. 23°33'21.0" N., Long. 119°59'27.1" E.

Lat. 23°33'11.0" N., Long. 119°59'34.2" E.

Lat. 23°33'11.1" N., Long. 119°59'21.8" E.

Lat. 23°33'14.2" N., Long. 119°59'27.9" E. \*WGS84

*Maritime and Port Bureau, MOTC*  
*Director-General Yeh Hsieh-Lung*